Extensible brace for excavations, W. J. Dunn.... 456,649

a dynamo be changed into a motor? A. As a rule, A. Try old flour paste allowed to stand for several days, be used without change as a motor. 8. How long will and water. 100 gravity (telegraph) cells run a 16 candle power incandescent light (50 volts)? A. It is impracticable to cells. 9. How long will 200 cells do it? A. It is impracticable to run incandescent lamps with any number of gravity cells. 10. How many gravity cells would be necessary to charge a storage cell of dimensions 12× 12×12, and how long to do it? A. For charging a storage battery cell, four cells of gravity battery are required. It takes from 7 to 8 hours to charge a storage

recipe for fastening paper to the face of an iron pulley and how to make a good belt glue. A. Scratch the face of the pulley with a rough file thoroughly, so that there are no bright or smooth places. Then swab the surface with a solution of nitric acid 1 part, water 4 parts, for 15 minutes, then wash with boiling hot water. Have prepared a pot of the best tough glue that you can get; stir into the glue a half ounce of a strong solution tannic acid, oak bark, or gall nuts, as convenient to obtain, to a quart of thick glue; stir quickly while hot and apply to the paper or pulley as convenient, and draw the paper as tightly as possible to the pulley, overlapping as many folds as may be required. By a little management and moistening of the paper it will bind very hard on the pulley when dry, and will not come off or get loose until it is worn out. Use strong hardware wrapping paper.

(3214) W. R. asks: 1. How many sulphate of copper batteries would be needed to charge a storage battery for running an 8 candle power electric lamp? A. You will require 4 cells of gravity battery to each cell of storage battery, 2. Should the storage cells be arranged in multiple arc during charging process? A. It is probably best to make the storage and gravity cells up separately, as above suggested. 3. How long will they run above lamp before running out, if used 6 hours daily? A. Storage batteries will not run large lamps for much more than six hours daily. 4. In what time can they be charged after the first thorough charge? A. It requi es from seven to eight hours to charge a storage battery. 5. What is the best arrange ment for the sulphate of copper cells? Is the Edison Lalande battery a suitable cell for running an electric lamp? How many of these cells would it take to run an 8 candle power Edison lamp? Where can I find a full and extensive treatise on this last type of electric battery? A. Write the Edison Manufacturing Company, Orange, N. J., with reference to the Edison-Lalande batterv

(3215) E. L. asks if there is a school, preferably in the eastern part of the country, where a young man can take a short special course in electrical engineering without being required to pass the examination in the languages and higher mathematics which the regular colleges require? A. A special course in electrical engineering such as you specify would be best obtained in an electric manufactory or works of the exclusion of mathematics. You might address ent. Columbia College, of this city, Cornell University, Ithaca, N. Y., and the Stevens Institute of Technology, 'are used in the induction coil of the Blake transmitter Hoboken, N. J., for information as to any special or elective courses they may have in electricity.

(3216) C. W. writes: 1. Have you a paper or book on watch finishing? A. We can supply you with the following books on the subject you mention. The "Watch Maker's Hand Book," by Saunier, price \$3.50. "A Treatise on Watch Work," by Nel thropp, \$2.50. "The Watch and How to Repair It," \$1. See page 53 of catalogue, which we send by mail. 2. Would it hurt a person to take brucine internally? A. It is a deadly poison, one of the worst known to 3. Is there any difference between brucine and brucin? A. No; it is only a question of spelling.

(3217) E. B. asks for a cement or It requires a magneto to operate it. Kindly favor with a cement and composition. how to apply it to join a close-grained, hard, white marble slab, 8 inches deep by 2 inches thick, 4 feet long, rough-broken into two pieces about the middle of its length, forming a side piece for cradle of a grave, and being always exposed to the inclemency of the weather. A. You might try a cement formed of oxide of zinc mixed with a strong solution of chloride of zinc. It will have to be applied quickly to each half of the stone, and the pieces joined before the cement sets. It will probably be well to experiment on a small piece of stone before applying the cement to the marble.

(3218) J. S. M. asks, What size of wire is suitable for winding field and armature of dynamo deocribed in Supplement, No. 161, made size of cuts? A. It depends entirely upon what you intend to do with the machine. For general purposes, however, we think No. 20 on the armature and No. 18 on the field magnet would do for a series machine. 2. What can be put the machine with the machine. By Douglas Graham, M.D. Pp. 342. New York: J. H. Vail & Co. 1890. in whitewash for outdoor to increase its adhesive qualities? A. Try skimmed milk. 3. Has there been a genuine history of Stanley's travels in Africa published, and by whom? A. Scribner & Co. of this city publish Stanley's books.

(3219) N. J. asks: 1. Could you give me the recipe for a glue that will withstand water as wellas oil and alcohol? A. Marineglue is made by softening pure India rubber (unvulcanized) in benzole or naphtha. To one part of rubber originally used add ten to twenty and warm upon a water bath (or use a glue pot for this); apply by melting with a warm iron or wire on the surfaces to be united. Do not use a flame. Common glue may be melted with water and one-tenth its weight of bichromate of potash. Exposure to light makes it

any good dynamo for generating a direct current can Infusorians are quickly developed in an infusion of hay

(3221) T. W. J. asks (1) for directions for softening stone, so that it can be moulded into any derun a 16 candle power 50 volt lamp with 100 gravity sired shape, and again become hard as before. A. Stone cannot be softened as you describe. 2. What liquid (or chemicals) will produce the most intense heat? A Sulphuric acid and water produce heat far above the boiling point. The acid should be added slowly to the There is always danger in doing it.

(3222) J. H. R. asks: How can I detect adulteration in bone meal, or whether it is pure or adulterated? A. The only reliable way is by analysis. It (3213) C. E. N. and H. W. McC. ask a should dissolve without effervescence in nitric acid, but this is a very imperfect test.

> (3223) T. L. P. writes: In my daughter's house, being built from plans furnished by your architectural bureau, the floors, which are of white oak, have become disfigured by black stains, probably where damp iron in some way has been in contact with them. I suppose it is tannate of iron. Can you suggest some means of removing this discoloration? A. Try hydrochloric acid diluted with ten volumes of water. If this is not strong enough, try weak solution of oxalic acid. The idea is to use any remedy as weak as possible.

> (3224) O. C. K. asks: What advantages and disadvantages are connected with the use of balanced valves on steam engines as compared with the ordinary slide valve actuated by an eccentric attached to crank shaft? A. The advantages are comparative freedom from wear and ease of movement. There being but little friction on the steam chest face, the perfect fit of both faces is maintained, saving leakage, which is a source of economy in running and repair. The gain in power is very small. The di-advantages are only found in their complicated construction and liability to become deranged by inattention to adjustment, the balancing requiring steam tight yet free moving joints. Beth kinds being moved by eccentric and rod, there is no difference outside of the steam

(3225) M. E.-New York, Brooklyn, and Berlin are we believe the only cities that have general aystems of elevated street railways. In other cities there are spurs of elevated tracks, or viaducts, on which trains pass to depots, etc.

(3226) D. W. S. asks: 1. Will you please tell me how the lights should be connected in circuit of eight light dynamo (Supplement, No. 600) so I can use one or more at a time? A. The lamps should be connected up in multiple arc; the field magnet of the dynamo should have about four more layers of wire, and the machine should be connected up as a shunt dynamo. 2. If I should build a machine after the same pattern for 16 lights, and connect lights in multiple. could I burn one singly, the machine running normally A. Yes; if connected as a shunt machine, with the field magnet winding properly proportioned. 3. Also, can I sell this machine when finished, without infringement of any patent rights? A. This machine when built some kind. A college could not give a good course to with a wire armature core does not infringe any pat-

> (3227) A. F. F. asks: 1. What sized wires What is the length and width of the core, and of what is it made? Are both coils copper? Is the primary coil insulated? Is there anything placed between the two coils? A. Use No. 36 wire for the secondary and No. 20 for the primary. Use two layers in the primary and 10 or 12 in the secondary. Make the core of the coil of a bundle of fine annealed wire % of an inch in diameter and 3 inches long. The primary and secondary wires are insulated, and the two coils are separated by three or four thicknesses of writing paper wound around the primary. 2. What is an auxiliary magneto bell? Will it work on a line 11/2 miles long without using the regular magneto? A. An auxiliary magneto bell is an additional bell put into a telephone circuit.

> (3228) F. W. S. writes: A recent fire destroyed our entire stock; our safe preserved our books very nicely. Being enabled to unlock it readily by the combination, we now wish to know from a source of good authority if this safe would still preserve our books through a like fire, and if not, why? A. The preservative qualities of a safe depend chiefly upon the amount of water contained in the filling. Hence for this pur-pose plaster of Paris, alum, and other salts that hold a high percentage of water are used. If a safe is exposed to a high heat for a considerable time, a portion of the water will be driven out of the filling, and consequently

## NEW BOOKS AND PUBLICATIONS.

This is the second edition of a book first published in 1884. It has been revised and enlarged, and the present volume is designed to cover a full description of the best mode of applying massage and its physiological effects as a remedial agent for a far greater number of ailments than it has commonly been supposed to be available for. The effects of massage upon the internal organs, upon complaints peculiar to women. and upon affections of the nervous system, are treated with especial particularity, while rheumatism and joint afparts of pulverized shellac, mixing it with the benzole. fections and many other complaints are shown to be Rub the mixture well in a mortar, transfer to a cup, beneficially subjected to this treatment, the general comfort and satisfaction derived therefrom making this method of cure, wherever it can be employed, a really enjoyable one.

## TO INVENTORS.

in the market? A. Marine glue is sold by dealers in microscopic supplies.

(3220) F. C. writes: There is a preparation that when put on the glass of a cheap microscope shows animalcules, bacteria, etc. I think it is some highly fermentive substance like yeast, but have experimented without any success. If you can give me any information about it I will be exceedingly grateful.

## INDEX OF INVENTIONS

## For which Letters Patent of the United States were Granted

July 28, 1891.

	•	July	20,	1091	ι,			4444
AND	EACH	BEA	RING	G T	НАТ	DA	TE.	11111
[See ne	ote at end -	of list a	bout c	opies o	of these	pate	ents.]	FFGG
Adjust: Air for	able brack producing	et, G. H motiv	. Christ e ener	tenser gy, uti	n lizing c	om-	456,614	GGGG
Air for mea	r the pro ns for util lock. J. Sw	duction lizing co	of m	echan se <b>d, V</b>	ical pov Popp.	ver,	456,594 456,783	GG
Alloy, a Animal Annunc	able brack producing used, V. Po r the pro- ns for util lock, J. Sw anti-frictic s, horn tip ciator, W. ciator, pne- ures for m	on, C. B. for, T. C. Dilln	Miller Cumm	ins			456,898 456,887 456,803	G G
Armatu sett Ax han	ires for m	otors an	d gener d. Dide	rators	, N. C. I	Bas-	456,925 456,802	GGG
Axles, o	ehicle, A. dust cap for ro	Johnson or vehice Iling far	le, J. P n-tail, I	. Cutle	er Hill	·••···	456,766 456,566 456,570 456 647	H
Baling   Baling   Ball, F	dle faston ehicle, A. dust cap fo mill for ro e, wire, J. press, W. presses, do F. Atkins	R. Mose evice for son	ley	ting, ]	D. Lostu	tter	456,834 456,703 456,920	H
Bar. S Bar str	ee Hollow aightenin	bar. z machi	ne. rou	nd. L	. H. Brie	zht-	456,883	H
Barrels	upstairs,	device i	or car	rying,	S. G. F	ran-	456,829	H
Battery Bearing Bed. fo	T See Se	condary L. Teeto E. Steve						Н
Bendin Bicycle Bicycle	z, ball, A. lding, F. I g machine e, A. N. Th e wheel, C. l table reg	A. Har	eters.	hlon	•••••		456,774 456,604 456,815	H
Bin. S Bisulph Blowin	ee Flour hites, appa g engine, paddle att	in. ratus fo S. P. Wa	r maki	ng, N.	H. Bro	kaw	456,791 456,643	F
Boats, Boiler. Boiler of Boiler	paddle att See Stea cleaner, T making ap , sediment , steam lo	achmen in boile: . E. Jone	t for, l r. es	lehm d	х магх. 		456,846 456,894 456,918	H
Boilers Boilers Ker	, sediment	t trap fo	or, Abra	ms &	McGah team, V	an 7. C.	456,711 456,672	- 1
Book, C Book, r Book, r	See Expan	ix O. Tang	eman.	ur bol	t.		456,717 456,862 456,677	I I
Bottle Bouque	See Expan C. R. Brod receipt, C. shoe hee filling mac et holder, See Ballot th powder	hine, G R. A. T box.	Rehfu yrrel File bo	iss et o	ıl tibbon	box.	456,907 456,745	I I
Brace. Bracke Brake.	See External See External See Carl blacking, machine, 1888 See ner.	r box. ensible b ljustabl brake.	race. e brack Vehicle	et. e brak	e.			In In In
Brush a Burner	blacking machine, l See	W. J. Se M. Youi Hydroc	ott ng arbon	burn	er. L	 amp	456,911 456,610	I:
Button net	ner.  s to mate:  t	rials, sec . Leavit	uring s	bank,	W. E. I	Ben-	456,926 456,656	H H
Cannot Cannot	a. See Ph See Oil car n, A. R. Da dv. J. Turi	otograp 1. Paint avis	hic can can.	nera. 			456,808 456,864	K
Car bra Car bra Car bra	ike, F. Me ike, M. A. ike mecha	yer Yeakle nism, A	y J. Wr	ight	45	6 <b>,60</b> 8,	456,674 456,750 456,609	I I I I
Car cou	ipling, E. ipling, J. 1 ipling, L. ipling, C. 1	P. Caldy F. Frien Groff E. Seabi	vell d nrv	• • • • • • • • • • • • • • • • • • • •			456,809 456,562 456,858	I I L
Car mil Car rep Car sea	leage regi placer, D. l it or cushi	ster, C. C E. Shern on, H. S	. Gale lan . Hale.	et al			456,650 456,780 456,764	Į.
Car sta Car, sto Car ve	rter, P. Flock, J. F. ntilating weel, W. J.	ood Elder vindow,	F. D. G	lover		· · · · · · ·	456.561	I
Cars,	mechanisr	n for a	utoma	tically	opera	ting	456,635 456,601 456,9 <b>0</b> 4	I
							456,878 456,698	I I N
Case. Cash Te	ard boxes A. F. Bird ble, F. B. oad, J. R. See Tobac grister and dehorming	mercere eco case dindica implen	tor, D.	zht.ca W. Sci . N. Jo	se hie <b>k</b>	•••••	456,581 456,575 456,682	N N N
Ceiling Centrii Chocol	plate, W. fugal macl ate, prepa	H.Stochine, C. ring ste	chham. J. Jepp crilized	esen G. H	. Neuh	auss	456,654	N N N
Churn	s, extension J. S. Oste power, ha	na ana	IOOL, F	1. F. a	: A. G. I	BOII-	456, 89 456,854 456,839	N N
han Cigar b Cigar b	ounching rounching rounchi	nachine nachine	C. Bro J. Cor Bohan	wning nell	<b></b>		456,790 456,691 456,798 456,644	N N
Clamp.	See Jew ne clamp. B. J. ●'Q	eler's w Pipe cl uinn	amp.	mp. H	Cnitting	ma-		N
Cleane Clevis, Clip, C.	ne clamp. B. J. •'Q or curt ain r. See Bo A. D. Bru E. Soule	iler clea	ner.	E. L.	rerry		456,636 456,793 456,743	I I
	E. Soule. See San folding ma			ichar	dson		456,851 456,827 456,652	(
Clutch Clutch Coiled	, W. H. Jo and speed , friction, , friction, spring, P. ounter, W. itrator an nser, R. P.	W. B. F A. C. R C. Mors	losford ice				456,571 456,939 456,833 456,701	1
				J. Roc McB	lermone	i	456,852 456,923 456,835	I
Conder Coupling Crate,	nser regula nser, wate ng. See C folding, S.	r jet, E. Car coup W. Hu	Korting. H	ig Iose c	oupling	 . the	456,828 456,653	F
Curren	folding, S. nd collar l es of, J. K ator, sulky at motor,	. P. Pin , J. L. I alternat	e Butler ing, M.	Von	Dolivo-	Dob-	456,506 456,551	I
Cuspid Cutter	ors, swing . See Tw.	attach	ment fo	or, S. 1	Horsem	an	456,804 456,620	I I
H. Dentu Derric	Lorimer re, artificia k, windmil	al, W. H ll, T. O.	. Marsi Perry (	nall r)			456,730 456,626 11,181	I I
Boor c	heck, A. A	A. Page.					456,922 456,707 456,748	I
Door to Draw to Drawin Car	rack and l bars, manu ng instrun	hanger, ifacture ients, m	C. O. Pa of, J. ( agnetiz	arsons Freen ed he	ad for,	6,699, R. S.	456,841 456,70 <b>0</b> 456,553	H
Drier. Drill, J	See Graii Muirhea	d					456,770 456,560	ŀ
Drying Dust c Dye, a: Dyes, 1	ress, H. H gapparatu oilector, J zo, C. A. M making az	s, v. r. . J. Gera lartius o. C. A.	L. Smid ir <b>d</b> Martiu	B	45	6,627,	456,810 456,897 456,628	i I
V.	Popp	ngon M	Dingh		egulatio		456,593 456,877	I
: Electr	tional pur , F. W. Pr ic circuit t Feilbogen	reaker:	or seco	onaary	genera	tors,	456,708 456,889	I
Electr	ic circuit ( ic light cra ic wires.  a	ane, C. 1	appar. L. Shan ent for	k boles	for. E.	wes. Ver-	456,817 456,859 456,683	H
Electr Electr Bro	aetelc wires, c ical appa ooks	able bea	d for, l	J. H. ontroll	Balsley led, T.	L	456,611	1
Electri Electri Electri Elevat	cooks ical distril o-motive- ode for secor guard, ssing mach idering m	force re condary H. D. S	ystem gulator batter vift	or, M. , E. M ies, O.	Bentle C. Flick	y	456,888 456,612 456,558 456,641	١,
Embos Embro Engine	ssing mach oidering m e. See Bl e. Pumpi	nine, E. achine, owing s	Jaeck J. Irish Engine. ne. St	Gas	or vapo	r en-	456,724 456,573	
Engine Expan	e. Pumpi e bearing, ision bolt,	Babbitt R. McG	& Bail	ey		• • • • • • • • • • • • • • • • • • •	456,921 456,589	<sub>]</sub>

	Feed water heater. J. Baird	456,905 456,905 456,563 456,713
	Feedwaterheater, locomotive, F. L. McGahan Fence, H. C. Pratt. File box, Osborn & Foster	456,676 456,637 456,591 456,797
	Firearm lock, F. D. Granger	456,813 456,687 456,776
	Flour bin and sifter, J. D. Field Flour bolt, O. M. Morse. Food compound, G. F. Ordway. Food rost J. N. Darby	456,720 456,806 456,554 456,903 456,567
	Forging car coupling hooks, die for, J. Green Fork. See Hay fork. Fruit and vegetable scoop and knife. E. O. Varell	456,892
	Furnace. See Reverberatory furnace. Gauge. See Micrometer gauge. Water gauge. Gas lighter, automatic electric, A. Wunderlich Gas lighter, electric, A. Wunderlich	456,68 <b>5</b> 456, <b>6</b> 8 <b>4</b> 456,8 <b>5</b> 3
	Gas retort charger, A. Hickenlooper	456,569 456,729
	Gearing, toothed, M. P. Campbell	456,796 456,844 456,837
	Grain bins, shout alarm for W.G. Adams	456,667 456,782 456,733 11,180
	Guns, reservoir for pneumatic, H. Eichbaum	456,617 456,819 456,850
	Hammer, power, C. M. Collins. Hanger. See Eaves trough hanger. Harvester, corn, McClure & Fri	456,616 456,657
İ	Tions	456,825 456,706 456,785
	Hay fork or grapple, C. Lardner	456,624 456,633 456,845 11,182
	Heater. See Feed water heater. Water heater. Hoisting and conveying apparatus. C. L. Saun-	456,831
	ders	45 <b>6,64</b> 0 456,7 <b>6</b> 3 456,9 <b>0</b> 8
	Nipple holder. Punching machine work hold-	456,646
	Horse boot, M. Barnes	456,786 456,688 456,816
•	Hose coupling, C. L. Bastian.  Hose coupling, C. L. Bastian.  Hydrocarbon burner, Blasdel & Morse	456,816 456,613 456,756 456,747 456,583
	Horse deacher and brake, A. H. Chilton. Hose coupling, C. L. Bastian. Hot water heater or boiler, E. D. Weston. Hydrocarbon burner, Blasdel & Morse. Ice cream freezer, Rube & Bartholomew. Ice shaving machine, F. O. Opitz. Incrustation preventive, J. Efrem. Incubator, A. H. Burr. Indicator. See Speeg indicator.	456,910 456,839 456,760 456,794
		456,607 456,544 456,602
	Insulator, span wire, W. S. Jarboe et al	456,574 456,600 456,645
	Wnife See Dogled Imide	456,658 456,891 456,662
	re- 144.	456,618 456,710 456,807
	Ladder, extension, J. E. Gillespie Lamp burner, J. E. Bohner Lamp, electric arc, F. L. Sautter	456,651 456,881 456,596
	Knitting machine clamp, S. Thurstensen. Knob a tlachment, C. L. Fitch. Knockdown table, E. G. Asmus. Ladder, extension, J. E. Gillespie. Lamp burner, J. E. Bohner. Lamp, electric ar c. F. L. Sautter. Lamp extinguisher, J. B. Greenhalgh. Lamp sture, J. E. Bohner. Lamp, oil, F. F. & S. Townsend. Lamps, letter displaying device for, Barringer & Johnston. Lands for reclaiming overflowed. T. F.	456,814 456,880 456,642
:	Johnston. Lands, means for reclaiming overflowed, T. F. Wurts. Lantern A. L. Baron.	456,750 456,749 456,721
i	Wurts. Lantern, A. L. Baron Lantern, A. H. Crawford. Life preserver, C. A. L. Kopcke. Lock. See Alarm lock. Firearm l ck. Seal lock.	456,721 456,621
	Lock, W. H. Taylor	456,917 456,550 456,676
	Butter.  Loom shuttle raceway, G. C. Moore.  Loom temple, E. S. Stimpson.  Lubricator, E. D. Bangs.  Machine wrench, M. Martin.  Magnetic separator, D. E. Leip.	456,916 456,714 456,830
!	Mail bag catcher, S. Wampler.	456,668
	Mast jury A. McDougall. Mast tenderer, J. L. Fugate. Medical induction col. H. A. Voelkner. Micrometer gauge, S. H. Bellows. Mill. See Grindling and amalgamating mill.	456,670 456,740 456,875
	Mill. See Grinding and amalgamating mill. Quartz mill. Mirror, adjustable, J. & M. B. Elbert. Money order, safety, H. W. Campbell. Mop wringer, J. P. Reuter. Mop wringer, C. A. White. Motur. See Current motor. Mower, J. F. Steward. Music holder, C. H. Reynolds. Nail puller, A. F. Street. Newspapers, machine for folding and mailing, J. E. Sawn.	456,698 456,889 456,77 456,666
	Mop wringer, C. A. White	456,666 456,783 456,638
	Nail puller, A. F. Street.  Newspapers, machine for folding and mailing, J.  E. Sawn.  Nipple holder, H. B. Spancer	456,638 456,500 456,599
	Newspapers, machine for folding and mailing, J. E. Sawn. Nipple holder, H. B. Spencer. Nozzle for street sprinklers, W. H. Miller. Numbering machine, E. G. Bates. Oil and making the same, drying, N. H. Finley. Oil and regulating the action of hydrostatic presses, process of and apparatus for expressing, J. H. Valle. Oil can ard siphon pump, T. Bumann.	456,599 456,860 456,769 456,870 456,890
	es, process of and apparatus for expressing, J. H. Vaile.  (i) can and siphon pump, T. Bumann	456,60 456,75
	Organs, combination stop action for, L. D. Morris Pad. See Inking pad. Truss pad. Padlock, W. E. Sparks.	456,74 456,68
	Paint, vulcanized, L. W. Osborn. Paper, coin-operated machine for furnishing toilet, B. B. Babbitt. Pastebaard articles, manufacture of, T. Remus. Pasteboard boxes, machine for connecting the	456,659 456,59
İ	Pasteboard boxes, machine for connecting the corners of, Saltzkorn & Nicolai.  Photograph apparatus, coin-controlled, F. Martin Photographer's retouching and marking apparatus.	
	rasteodara oxes, inactine for connecting the corners of, Saltzkorn & Nicolai.  Photograph apparatus, coin-controlled, F. Martin Photographer's retouching and marking apparatus, C. Cutler.  Photographic exposures, instrument for calculating. A Wetkins.	456,555 456,845 456,845
	ing, A. Watkins.  Pipe clamp, J. Muirhead.  Pipe connection, N. E. Smith.  Pipe covering, steam, C. J. W. Shearer.  Pipe, manufacture of lead lined iron, G. W. Harrington.  Planing, machines, rotary cylinder and cutting	456,76 456,76 456,78 456,66
	rington  Planing machines, rotary cylinder and cutting knife for S. Brb.  Brown   456,92°	
	Planter, corn, C. J. Brown. Pocket knife, C. Gerlach. Post hole digger, F. E. Kohler. Power. See Churn power. Press. See Baling press. Cake press. Drill press. Hay press. Printing press. Printers' rollers, apparatus for making, L. K. Rincham	456,76 456,54 456,81 456,65
	Printing press, os cillating cylinder, W. Scott Printing press sheet delivery apparatus, C. B. Cottrell Protector See Circuman's smoke protector Wall	456,87 456,74 456,66
	protector.	456,72 456,73
	Pumping engine, duplex, E. Barnes	456,75 456,57 456,57
	Pulley, W. H. Dodge. Pulley, W. H. Dodge. Pulley, Wershon & Richters. Pumping engine, duplex, E. Barnes	456,82 456,62 456,72
i	Quilting machine, L. Schultz456,734 to 456,738, Rack. See Feed rack. Radiator, steam or hot water, T. C. Joy456,895, Railway, W. S. Herrington	456.81
	Railway carriages, brake for elevated, J. N. Val-	400,00
		456,75
	Rover	456.86