## Business and Personal.

The charge for Insertion under this head is One Dollar a line nsertion; about eight words to a line. Advertisements must be received at publication office as early as Thursday morning to appearin the following week's issue

Order pattern letters & figures from the largest varie ty. H. W. Knight & Son, Seneca Falls, N.Y., drawer 1115 "U. S." metal polish. Indianapolis. Samples free. Stave machinery. Trevor Mfg. Co., Lockport, N. Y.

Steam Disinfectors. Geo. T. McLauthlin & Co., 120 Fulton St., Boston, Mas Universal and Plain Milling Machines. Pedrick & Ayer, Philadelphia, Pa.

Wm. Jessop & Sons have a handsome display of steel in Mining building at the World's Fair.

The Improved Hydraulic Jacks, Punches, and Tube Expanders. R. Dudgeon, 24 Columbia St., New York.

Stow flexible shaft. Invented and manufactured by Stow Mfg. Co., Binghamton, N. Y. See adv., page 30. Screw machines, milling machines, and drill presses, The Garvin Mach. Co., Laight and Canal Sts., New York

Centrifugal Pumps for paper and pulp mills. I rigating Wanted-Capital to develop a patent. For sale, two patents, in whole or part. "Develop Patent," 11 Washington Street, Newark, N. J.

Guild & Garrison, Brooklyn N. Y., manufacture steam pumps, vacuum pumps, vacuum apparatus, air pumps. acid blowers, filter press pumps. etc. Split Pulleys at Low prices, and of same strength and

appearance as Whole Pulleys. Yocom & Son's Shafting Works, Drinker St., Philadelphia, Pa. Hydraulic wheel presses, hydraulic platen presses, and special hydraulic machinery. The J. T. Schaffer

Mfg. Co., Rochester, N. Y. See adv., page 78. Perforated Metals of all kinds and for all purpo general or special. Address, stating requirements, The

Harrington & King Perforating Co., Chicago. The best book for electricians and beginners in electricity is "Experimental Science," by Geo. M. Hopkins.

By mail, \$4; Munn & Co., publishers, 361 Broadway, N.Y. Canning machinery outfits complete, oil burners for soldering, air pumps, can wipers, can testers, labeling machines. Presses and dies. Burt Mfg. Co., Rochester, N. Y.

Competent persons who desire agencies for a new popular b.ok. of ready sale, with handsome profit, may apply to Munn & Co., Scientific American office. 361 Broadway, New York.



HINTS TO CORRESPONDENTS.

Names and Address must accompany all lette s, or no attention will be paid thereto. This is for our info mation and not for publication.

References to former articles or answers should give date of paper and page or number of question.

Inquiries not answered in reasonable time should be repeated; correspondents will bear in mind that some answers require not a little research, and, though we endeavor to reply to all either by letter or in this department, each must take his turn.

Special Written Information on matters of personal rather than general interest cannot be expected without remuneration.

Scientific American Supplements referred to may be had at the office. Frice 10 cents each.

Books referred to promptly supplied on receipt of price.

Minerals sent for examination should be distinctly marked or labeled.

(5249) H. M. W. says: A friend of mine, a practicing physician, carries a tie weight in the front of his buggy and it continually winds up the strap. The movement is from right to left or against the sine. It does not seem to matter how the buggy is loaded. Can you explain the phenomenon? A. The turning is probably due to jarring of the vehicle and slight projections on the bottom of the weight.

(5250) W. V. S. asks: Will water boil in a pot set in another pot of boiling water? If so, how? A. No; not unless you put salt in the water of the outer kettle. Brine boils at a higher temperature than water.

(5251) J. McG. asks how to make brewer's yeast. A. Brewer's yeast is prepared as follows: 72 pounds unkilned malt and a handful of hops are gradually stirred in a clean tub containing 7 gallons of water of 170° Fah, and to this 516 gallons of water of 200° are added. The tub is then covered tightly and left quiet. After some time it is cooled rapidly. This is accomplished by setting in cans filled with cold water. When the temperature of the mash has reached 70°, the tab is covered again and allowed to stand for some twelve hours longer, when 11/4 gallons fresh beer yeast are to be stirred in. After another twelve hours have clapsed, pierce a hole in the layer fo med by the husks of the malt and dip 31/2 gallons of the liquor beneath, then stir the whole up and dip 134 gallons from it (husks and liquor). This is the mother leaven, from which yeast can be generated all the year round by using it in the way described instead of the ordinary beer leaven. To the remainder in the tub add 5 gallons wort of 90° and make use of it within two hours. The mother yeast also must be used the same day for fermenting another portion.

(5252) A. E. L. asks how to make skeleton leaves. A. A quick method is as follows: Four ounces sal soda are dissolved in 1 quart hot water, 2 ounces quicklime are added, and the whole boiled for twenty minutes. The solution is cooled and strained. a very small dynamo that will light one or two Edison The leaves are then boiled in this for one hou, or until standard lamps, but you will find in Supplement, No. the pulp is easily removed, when it is washed off as already mentioned. The fibers remain, leaving a perfect skeleton or framework of the leaf. This is bleached by exposure to a solution of 1 tablespoonful of chloride of lime in 1 quart water, strained clear from sediment. The skeletons are placed in a dish, covered with this solution and kept in a dark closet for two days, watching in the meantime that the fibers are not softened too much and thus injured. After bleaching, the leaves are steeped in clear soft water for a day and then floated off upon a card and placed between soft napkins until dry. They are then ready to be finally pressed, bent, curled, or arranged in bouquets or groups.

(5253) C. H. J. asks: 1. Will you ino m me if the first charging forms the storage cell described in Scientific American of March 4, 1893, page 134, or is a more complicated process necessary, and what is the process? A. To form a storage cell it is necessary to charge it and discharge it several times, each time reversing the charging current. After it is formed it should always be charged with the current passing in the same direction, and that should be the same as last used in forming. 2. Is it necessary to fo m them with a bichromate cell or can it be accomplished with the gravity? A. You can fo m them more rapidly with a bichromate cell or dynamo than with gravity cells. 3. Should the gravity be connected in series, and how should the storage be connected when charging and discharging? A. The cells should be connected in series, four gravity cells to each cell of storage battery. 4. Is it possible to charge two sets of secondary cells separately and then to discharge them connected together in series, etc., and would the time of charging of the two or more sets have to be exactly the same? A. The batteries can be charged in this way, but they should be charged to the samevoltage. 5. How longwould it take 16 gravity to charge 4 storage and would the 16 gravity charge any more than 4 storage and sand pumpingplants. Irvin Van Wie, Syracuse, N. Y. at a time? A. It would take from 8 to 10 hours to charge the storage cell. You could not make a more advantage ous combination with 16 cells.

> (5254) A. G. G. asks (1) why the water of a whirlpool always flows in a direction contrary to the hands of a clock? A. A whirlpool may have either direction of rotation. 2. Is there any method of nickel plating without the aid of batteries? If so, how? A. On some bases a coating may be produced without a battery, but it will not be a satisfactory one. 3. What are eye stones? Are they supposed to possess life? A. They are the opercula (closing or door shells) of certain shell fish (turbinidæ). Their action on the eye is mechardcal. They are devoid of life.

> (5255) W. S. asks: How is phthalic acid (anhydrous) made ? A. By acting on naphthalene, alizarin or purpurin with nitric acid, phthalic acid  $(C_8H_6O_4)$  is produced. By heating this to a temperature exceeding 365° Fah., phthalic anhydride ( $C_8H_4O_3$ ) is produced.

> (5256) W. H. J. asks: 1. Is the term horse power, used as a unit of power, in estimating the efficiency of a steam engine, equivalent to the horse power of 746 watts used by electric engineers? A. Yes. 2. Can a steam engine of say 10 horse power drive an electric generator and produce more than 10 horse power of electric energy? What per cent gain or loss of power would occur? A. A loss of from ten to twentyfive per cent maybe anticipated.

> (5257) E. C. J. writes: I am making an electrical machine consisting of a glass wheel and rubbers. I should like to know in what way I could fasten the wheel to a brass axle so that the wheel could bear a great strain when turned. I thought of getting a flange to screw uptight to the glass on either side, but I fear it will break the glass. Could a cement of some kind be put between the flange and the glass? If so, please state what kind and its preparation? A. You can clamp your glass disks between collars on the shaft as you propose without danger of breaking the glass, provided the glass is flat. We would suggest a cement of plaster of Paris put between the flanges and the glass.

> (5258) H. J. S. asks: Which will take themost force, the pipe running up outside and running the water in at the top or with the pipe screwed in the bottom of the tank? A. It requires the most power to pump the water over the top, by the difference in pressure between the level of the water in the tank and the inlet pipe added to the friction of the additional pipe to carry the water to the top. This amounts to 0.43 of a pound pressure for every foot of height between the level of the water in the cistern and the mouth of the pipe at the top. The friction of a few feet of pipe is small, but still a factor of lost power in a discuss

> (5259) Richmond says: If you take a tub of water weighing 50 pounds (tub and water), the tub being half full of water, and put a 5 pound live fish in the tub of water, none of the water being forced out, will the tub of water weigh any more with the live fish in it than it will without it? If so, how much, and how do you account for it? A. The tub, water, and fish will weigh exactly 55 pounds. This old yarn has been an swered many times in this journal and many more directly. We are in hopes that some of our readers will eventually get out of this class of ruts, take to the physical facts of nature, and come to the conclusion that nothing comes from nothing and that one and one makes two every time. Everything that has weight when added to a weight increases the weight, whether animate or inanimate, fluid, air or gas.

> (5260) J. H. R. writes: I have an electric bell from tank to house that rings when tank is full; the connection is made under water by a float pulling a brasswire against a copper wire above it. The copper wire will corrode in a few hou s, so that a connection will not be made. Will you kindly help me out? A tank. This you can readily do by connecting a rod with the float.

> (5261) E. L. writes: 1. I saw in your last Supplement to Scientific American averygood description of how to make a cheap and simple electric motor. Now I ask is it possible to make likewise a dyname of such simple pattern, for running one or two Edison standard lamps? A. We have no description of 844, a detailed description of an Edison dynamo for nine lamps. 2. I have got a small electro-magnet, used for medical purposes; the magnet does not work properly. How or where can I get it charged again? A. You can have your permanent magnet recharged by any electrician, or it can be recharged at any electric light station.

> (5262) J. B. asks: Is there any way to harden steel castings, can they be tempered? A. Steel castings can be case-hardened by the same process as for

(5263) J. H. S. asks: What amount of horse power can I get from an underflow wheelin a

stream with a current 41/2 miles an hour, 100 feet wide, 3 feet deep, the wheel to be 20 feet diameter, 24 feet wide, paddles  $2\times24$  feet, with a cable wheel 10 feet diameter, to convey power 150 feet distant? Also how fast will the wheel run when power is on? A. Wheel should run at a peripheral speed of one-half the water velocity. or 614 revolutions per minute, and should transmit 8 horse wer through the cable

(5264) B. A. M. asks: How can canvas be made mildew-proof at a small expense? A. Immerse the canvas in clear tan bark liquor, of about the strength of 1 pound oak bark to 4 gallons water, boiled settled and decanted, for a few hou s, then rinse and dry. This will give the canvas a slight color. A wash of alum water 1 pound to 4 gallons water answers a good purpose and does not change the color.

(5265) H. S. asks for a receipt for that kind of bress that is commonly known as gun metal. It is used for the hubs of bicycle wheels. These castings are done at a very low price (about eighteen cents per pound). I would like to know how it can be done. A. The best gun metal is an alloy of 9 parts copper, 1 part tin, by weight.

(5266) L. C. D. asks: 1. Is there any satisfactory explanation of why a ball can be made to curve being delivered from the hand of a pitcher? A. The throwing of a curved ball is illustrated and explained on scientific principles in Scientific American Sup-PLEMENT, Nos. 402, 410, 423, 10 cents mailed. 2. Peculiar treaks in electricity are often seen in the shape of luminous balls which move comparatively slow, and if they strike a wooden surface, will bound off. They are, I think, called St. Elmo balls. Can you explain the phenomenon? A. St. Elmo's fire is a peculiar condition of low electric intensity in the atmosphere, such as often occurs in fair weather, when by supposed induction and insulation, pointed objects projecting above surrounding objects become surcharged with the electric fluid and a brush discharge takes place, without audible noise, but with a feeble luminous glow. It has been observed on spires, on the masts and spars of ships. 3. Does electricity stream on as well as off a point? If it does not, does a lightning bolt go from the cloud or vice versa? A. Electricity passes in the brushformof discharge from generating surfaces to conducting surfaces when of low intensity, and both ways between conductors. The lightning bolt occasionally passes upward by the reverse atmospheric conditions as to polarity.

(5267) C. S. asks: In regard to deep wells, which water would be the most healthy, that out the black iron casing pipe or out of the galvanized casing? A. Water that is constantly flowing from a deep well pipe is equally healthy from both black and galvanized pipe. If the water is checked for a time without flow, the water from the black pipe may become charged with iron and will not be palatable, although healthy, while water standing in the galvanized pipe becomes charged with zinc oxide, which is poisonous. If then, the contents of the pipe is drawn off, the following water will be good.

## Replies to Enquiries.

The following replies relate to enquiries published in the Scientific American, and to the numbers therein

(5186) Referring to SCIENTIFIC AMERIcan of July 15, page 45, paragraph 5186, will you please say to G. L. F. that if he will plant tansy about the trunks of his plum trees, a good thick growth of it, the fruit will not be stung. As the plums ripen, the skin will be coated with a so t of frosting or bloom bitter to the taste, but easily rubbed off. Fifty-odd years ago I noticed this in my father's garden, about a wild plum transplanted from the woods. I think it never failed to yield an abundant crop, the fruit increasing in size and quality. The tansy was supposed to spread several feet from the tree trunk. If, upon trial, G. L. F. is pleased with result, he will oblige the public, and I hope Professor Riley especially, who has done so much for the cultivators of fruit and grain, flowers, etc., by asking the Scientific American to acquaint the world with this simple remedy.-G. W. DEVIN, Ottumwa, Iowa, July

## TO INVENTORS.

An experience of forty-four years, and the preparation of more than one hundred thousand applications for patents at home and abroad, enable us to understand the laws and practice on both continents, and to possess uncqualed facilities for procuring patents everywhere. A symposis of the patent laws of the United States and all foreign countries may be had on application, and persons contemplating its securing of patents, either at home or abroad, are invited to write to this office for prices which are low, in accordance with the times and our extensive facilities for conducting the business. Address es for conducting the business. Address office Scientific American, 261 Broad-MUNN & CO., o way, New York.

## INDEX OF INVENTIONS

For which Letters Patent of the

August 1, 1893,

AND EACH BEARING THAT DATE.

[See note at end of list about copies of these patents.]

cid combinations, obtaining meta or pyro phos-	
phoric. H. Precht	502,424
phoric, H. Prechtdvertisements, apparatus for distributing, F. B.	
Cochranerating distilled water, Thomas & Grow	502.390
erating distilled water. Thomas & Grow	502,409
erating distilled water, apparatus for, Thomas	
& Grow	502,409
annuclator, electric, T. Spencer	502.472
utomatic brake, E. A. Merriman	502,526
xle box, car, R. Brewer	502,652
ag. See Mail bag.	000,000
nime of I W (1) honey	509 433
alance, J. W. Gibboney. ale or bundle wiring tool, G. Schubert	102.328
all throwing or bowling machine. Keane & Wil-	002,000
and thiowing of now link machine, wearte of Atti-	502,299
sonarrel washer, J. W. Flower et al	509,200
atteries, electric cells, etc., box for secondary,	00#,217
There's, electric cens, etc., box for secondary,	502,643
Theryc & Oblasser	002,050
attery. See Galvanic battery.	509 00d
ed, folding, P. Flowers	FOO 406
eablye, D. A. Dewey	000,000
ell, door, C. M. Burgess	0012,612
loy cle support, H. J. Hyams	004,748
tine or boxes, automatic drop lid for, B. Dailey	XXX.600

Bituminous rock, apparatus for reducing an soft ening, E. Groat	502,416
ening, E. Groat. Blind stop, W. W. Hoskins.	502,417 502,362
Boiler furnace, steam, A. B. Cosby	502,640 6, 502,617 502,493
Bituminous rock, apparatus for reducing an soft ening, E. Groat. Bituminous rock, machine for reducing and soft ening, E. Groat. Bind stop, W. W. Hoskins. Biotter, J. H. Russell. Boller furnace, steam, A. B. Cosby	502,365 502,423
Box. See Letter oux. Faper box. Spice box. Box forming machine, W. S. Rice Brake. See Automatic brake, Car brake. Ve	502,320
Brake. See Automatic brake. Car brake. Vehicle brake. Bridge and door, combined stock, H. O. Dorn. Bridge gat a Follet & Simpson. Brush horse, E. Giesecke. Buggy top spring aupport, S. Bougie. Buggy top support, S. Bougle. Bushing and faucet, G. H. Merrick. Butter worker and mould, E. S. Boynton. Button and link, combination cuff, L. S. Sampso. Calendar, W. K. David. Can. See Oil can. Self-closing can. Can labeling machine, C. A. Burt. Car torake, Sullivan & Osborn. Car coupling, T. G. Blackman, Jr. Car coupling, T. M. M. Hall. Car coupling, H. M. M. Lefever. Car coupling, H. M. M. M. Car coupling, T. G. W. & H. F. McMillen. Car coupling, E. Sangent. Car coupling, F. Sangent. Car coupling, F. Sangent. Car coupling, F. Tiemann. Caramel holder, G. Miller. Cart, garbage, T. Dark, Sr. Cart, road, J. J. Cretsinger. Case. See Confectionery case. Cash register, L. Ebrlich. Cash register, L. Ebrlich.	. 502,510
Brush horse, B. Giesecke. Buggy top spring support, S. Bougie	502,603 502,606
Buggy top Support, S. Bougle Bushing and faucet, G. H. Merrick Button worker and mould S. S. Bownton	502,607 502,572
Button and link. combination cuff, L. S. Sampso Calendar, W. K. David	n 502,586 502,483
Can Isbeling machine, C. A. Burt	. 502,490 502,476
Car coupling, D. Bellon	502,660 502,274
Car coupling, W. M. Hall	. 502,296 . 502,304
Car coupling, A. B. Lefever. Car coupling, H. H. Martin.	502,306 502,309
Car coupling, J. M. McMaster. Car coupling, C. W. & H. F. McMillen	502,631 502,499
Car coupling, F. Sargent Car coupling, F. Tiemann.	502,582 502,596
Cart, garbage, T. Dark, Sr. Cart, road, J. J. Cretsinger	502,360 502,281
Cash register, C. Baseigh	502,853
printer, P. Pfeifer.  Cash register, recorder, and indicator, electrical	. 602,317
Cash register and indicator, A. H. Scranton Cash register, indicator, recorder, and chee printer, P. Pfeifer. Cash register, recorder, and indicator, electrical L. Ehrlich Cash registering machine, J. J. Webster Churn, Elliott & Crigler Churn, R. A. Ludlow. Cider mill, C. W. & E. G. Geet. Clamp. See Furniture clamp. Clock synchronizer, electric H. S. Prentiss.	502,645 502,286
Churn, R. A. Ludlow. Cider mill, C. W. & E. G. Gest.	502,628 502,558
Clock synchronizer, electric, H. S. Prentiss	. 502,381 8, 502,647
Clock synchronizer, electric, H. S. Prentiss. Clothes wringer, C. Wheeler, Jr. Clutch, friction, Nottingham & Tucker. Coal handling appliance, H. K. Morrison. Coal piling apparatus, J. M. Dodge. Cold and ice, apparatus for producing, E. D. Keu	502,445
Cold and ice, apparatus for producing, E. D. Ken dall	002,505  -   502,439
Collar, horse, E. R. Williamson. Collar or cuff blank folding machine, G. E. Harri	502,543 a 502,678
Confectionery case, C. B. Overbaugh	502,474 502,634 502,559
Corkscrew, match holder, etc., combined, P. Dea Corn shock binding device, H. Johnson	n 502,351 502,672
Cotton press, J. L. McCutcheon. Coupling. See Car coupling. Pipe coupling. Shaft coupling. This coupling.	502,313 3.
Crate, folding shipping, C. A. Daniels	502.481 502,429
Crimping tool, F. C. Wilson	502,339 . 502,581 502,585
Cold and ice, apparatus for producing, E. D. Ken dall.  Collar, borse, E. R. Williamson.  Collar or cut bank folding machine, G. E. Harri Conduit, G. Sterling.  Confectionery case, C. B. Overbaugh.  Conveyer, C. S. Schenck, etc., combined, P. Dea Cornsorew, match holder, etc., combined, P. Dea Corn shock binding device, H. Johnson.  Cotto in Seas, L. McCouthelon.  Coughaft coupling. This coupling.  Crate, folding, S. J. Butters.  Cut and folder, E. E. Chapman.  Curtain rod and bracket, J. Day.  Cuttain rod and bracket, extension, Brothwell of Phillips.	. 502,456 . 502,659
Curtain rod and bracket, extension, Brothwell (Phillips.	£ 502,654
Curtain rod and bracket, extension, Brothwell of Phillips. Cuspidor, C. R. McComb. Cut-out, automatic, C. Hoffmann. Cut-out, fusible, E. Thomson. Cutter. See Paper cutter. Thrashing machin band cutter.	502,518 502,330
Cutter. See Paper cutter. Thrashing machin band cutter.	e 500 990
Cycle speed multiplying mechanism, H. Treprea Cycle wheel, A. Perkins	602,500 502,852
Dice shaking machine, coin-controlled, O. G. Klugel.	5(12,496
Direct-acting engine, W. H. & M. R. Rust. Dirt or garbage receptacle, P. W. St. George. Disinfecting or vaporising device, Woodcock & Kingzett.	. 502,696 E
Kingze tt.  Door hanger, T. C. Prouty.  Doweling, method of and machine for, H. Camp	. 502,544 . 602,582
bell	. 502,656
Dell. See Grain drill. Rock drill. Dust pans, folding handle for, E. L. Hiatt. Dye, black azo, Lauch & Krekeler.	
Dye, green-blue alizarin, R. Bonn.  Dye, reddish-blue azo, Lauch & Krekeler  Electric cable, T. Guilleaume	502,369 502,358
Von Siemens.	502,689
Electric machine, magneto, F. X. Hofbauer Electric machine or motor, dynamo, H. J. Ryan.	502,670 502,384
Electric regulator, D. M. Moore Electric motor or dynamo, S. Paugh	502,444 502,877
Elevator, N. Beckwith Elevator controlling device, C E. Moore.	502,27.1 502,972
Elevator hoisting mechanism, C. E. Albro Elevators, electrical indicator for E. E. Peirce.	502,600 502,315
Dell Drill. See Grain drill. Rock drill. Dust pans, folding handle for, E. L. Hiatt. Dye, black & Zo, Lauch & Krekeler. Dye, green-blue alizarin, R. Bohn. Dye, reddish-blue azo, Lauch & Krekeler. Electric cable, T. Gullleaume. Electric currents, distribution of alternating, W. Von Siemens. Electric distribution, system of, E. M. Bentley. Electric machine or motor, dynamo, H. J. Ryan. Electric motor or dynamo, S. Paugh. Electrical heater, C. E. Jones. Elevator, N. Beckwith. Elevator controlling device, C. E. Moore. Elevator hoisting mechanism, C. E. Albro. Elevators, electrical indicator for, E. E. Peirce. Embossing machine, R. S. Anderson. Embossing machine, R. S. Anderson. Embossing machine, R. S. Anderson. Empines, steam distribution in triple-expansion F. M. Rites. Envelope, safety, J. J. Gleason. Excavator, E. Kuud Fence, J. A. E. Anderson. Fence and stay, D. Bryan. Fence post, A. C. Harrison. Fencing, metallic, I. Ellwood. Filter, hag, T. O. East on & a. Filter hag, T. O. East on & a. Filter hag, T. O. East on & a. Filter hag, and and the filter hag, and the filter hag. Frod, machine for the preparation of cereals for Perky & Ford. Frod, machine for the preparation of cereals for Perky & Ford. Frod, machine for the preparation of cereals for Perky & Ford.	502,463
Engine. See D rect-acting engine. Gas engine Pumping engine. Rotary engine.	).
F. M. Rites	. 502,501 . 502,560
Excavator, E. Ruud. Eyeleting machine, E. B. Stimpson.	502,469 502,327
Fence and stay, D. Bryan. Fence post, A. C. Harrison.	502,343 502,345 602,523
Fencing, metallic, I. L. Ellwood. Filter, bag, T. O. East on et al.	502,512 502,511
Filtering apparatus, water, D. A. Rankine Filtering apparatus, water, D. A. Rankine Fly book, angler's, A. E. Zangonhorg	. 502,690 . 502,693 . 509,497
Food, machine for the preparation of cereals for Perky & Ford. Furnace. See Boiler furnace. Gas furnace. Sal	502,878
Furnace. See Boiler furnace. Gas furnace. Sal furnace. Furnace for heating chain link blanks, etc., fo	r F
Turnace. Furnace for heating chain link blanks, etc., fo welding, P. H. Standish. Furnace for heating chain links, P. H. Standish. Furniture clamp or press, C. H. Scales. Fuse, electric safety, C. Tbalacher. Fuse, multiple, G. T. Voornees. Gauge. See Jewel and pivot gauge. Galvanic battery, E. H. Lvon.	502, <b>593</b> 502, <b>594</b>
r urniture ciam p or press, C. H. Scales Fuse, electric safety, C. Thalacher Fuse, multiple, G. T. Voorbees	502,541 502,541 502,333
Gauge. See Jewel and pivot gauge. Galvanic battery, E. H. Lyon.	. 502,405
Galvanic battery, E. H. Lyon. Game apparatus, M. B. Andrews. Gang plank, warehouse, L. Kuckartz Garment fastener, D. M. Floerckey. Garment supporter, J. W. Beaumont. Gas engine, carbonic acid or other, Danner in Rothenbucher. Gas furnace parlor, J. W. Cownerthwait.	502,456 502,668 502,499
Garment supporter, J. W. Beaumont. Gas engine, carbonic acid or other, Danner	. 502,333
Rothenbucher. Gas furnace, parlor, J. W. Cowpert bwait Gas illuminating bydrobarbon, E. Tatham	502,430 502,668 502,642
Gas, illuminating bydrobarbon, E. Tatham. Gas meter, J. B. Wallace. Gas miter, G. A. Roberts. Gate. See Bridge gate. Railway crossing gate.	507.388 502.531
DIVERSITY TO A TO	502,460
Glove or garment fastener, E. J. Kraetzer	502,404 502,404 502,557
Glass article and makin same, ornamental, J. E. I. E. I. E. I. E. I. Glove or garment fastener, E. J. Kraetzer. Governor, speed, C. E. Doolittle. Grate, W. S. Dobbs. Grater, vegetable, R. Olp. Grain binder, J. F. Appleby. Grain binder, J. F. Appleby. Grain binder, A Stark. Grain frill, A. Resander.	. 502,554 . 502,527
Grain binder, J. F. Appleby	502,267 502,540 502,696
(1rain drill % W Rowall	FATE AND
Gun, breech-loading, L. L. Hepburu Gun carriage, disappearing, S. M. Mansfield Gun, gas-operated breech-loading, J. M. Brown ing.	. 502,569 . 502,540
ing Gun, magazine, Whitten & Porcher Hair crimper, C. A. Krutsch. Hair, machine for intersacing curled horse, F	502.389 502.567
Hair, machine for interlacing curled horse, F	. 502,376
Ocbs. Hanger. See Door hanger. Harrow. Anderson & Winston. Harrow. C. Perrin.	502,391 502,692
Harrow spring tooth. H. Gale Harvester, G. W. Scott	502,489 502,584
Heater. See Electrical heater. Heater, J. A. Weaver.	. 502,335
Harrow. Anderson & Winston.  Harrow C. Perrin.  Harrow spring tooth. H. Gale  Haryester, G. W. Scott.  Hay rake and loader, M. Rew.  Heater. See Klectrical heater.  Heater, J. A. Weaver.  Heel, H. Menier.  Heel, compressing and loading machine, C. W.  Glilden	. 502.571 7 509 660
Heel nail, G. A. Curtis	. 502,550
Hinge, combined strap and pivot, L. Lipp Hook, H. S. Piggins	. 602,306 . 562,529
Hele hannig machine, C. W. Graden. Hinge, combined strap and pivot, L. Lipp. Hook, H. S. Piggins. Hoop. See Mast hoop, Hoopmaking machine, Pleukbarp & Liggett Horse blanket, Cleveland & Tuller Horses, trip for releasing, C. C. Drake. Horseshoe, R. De Eicken.	502,407 503,508
Horses, trip for releasing, C. C. Drake	512,497 512,854